

Sunday, February 19. 2012

### **Provisioning and cleaning**

While I've been busy with repairs and installation and sorting through the contents of lockers, Liz was equally busy (if not more). She planned the provisioning, went shopping, organized the shelve space, and thoroughly cleaned the boat. Which included the bilge, which certainly hasn't seen that much cleaning in the last 30 years.

Provisioning spree!

Liz 1 : Dirty bilge 0

One of the weak spots of Gudrun is the permanently wet bilge, because of the mast that sticks through the deck. Any time it rains water runs down the mast and accumulates in the top of the keel. Any other items that fall through the cracks in the flooring also make their way there, as do any leaking fluids from the engine (e.g. when the oil cooler exploded). And of course it's hard to reach, e.g. my arms just don't fit through the crack.

Posted by Axel Busch in Gudrun V at 08:41